

Fisheries and Oceans Canada

Pêches et Océans Canada

Canadian Coast Guard Garde côtière canadienne

NOTICES TO MARINERS MONTHLY SUMMARY OF (T) AND (P) NOTICES

MONTHLY EDITION N°07 July 26, 2019



Safety First, Service Always

CANADIAN COAST GUARD

www.notmar.gc.ca



Notices to Mariners Monthly Summary of (T) and (P) Notices Monthly Edition N°07/2019

Published under the authority of:

Canadian Coast Guard Programs Aids to Navigation and Waterways Fisheries and Oceans Canada Montreal, Quebec H2Y 2E7

© Her Majesty the Queen in Right of Canada, 2019 DFO/2019-2031 Fs151-19E-PDF ISSN 2561-5106

Available on the Notices to Mariners website: www.notmar.gc.ca

Disponible en français : Avis aux navigateurs Sommaire mensuel des avis (T) et (P) Édition mensuelle N°07/2019

NOTICES TO MARINERS MONTHLY REPRINT OF TEMPORARY AND PRELIMINARY NOTICES IN EFFECT AS OF JULY 26, 2019

Geographical positions refer directly to the graduations of the largest scale Canadian Hydrographic chart unless otherwise indicated.

Bearings refer to the true compass and are measured clockwise from 000° (North) clockwise to 359°; those relating to lights are from seaward.

Visibility of lights is that in clear weather.

Depths - The units used for soundings (metres, fathoms or feet) are stated in the title of each chart.

Elevations are normally given above Higher High Water, Large Tides unless otherwise indicated.

EXPLANATION OF TEMPORARY AND PRELIMINARY NOTICES

Certain Notices to Mariners appearing in the monthly editions have a (T) or (P) appended to the regular number. These letters indicate that the information contained in the notice is of a temporary or preliminary nature.

TEMPORARY (T) NOTICES

If a temporary change in conditions affecting navigation exists and if the change will be effective for a period of over three months, a (T) notice will be published. Temporary changes which are effective for periods of less than three months will not normally be published (unless it is of exceptional interest). Otherwise, information will be broadcast as a Navigational Warning by the Canadian Coast Guard Marine Communications and Traffic Services (MCTS) centre of the area in question. (T) notices will be cancelled as necessary.

Please note that Temporary Notices (T) with an end date will be automatically cancelled once the end date has passed. In the event of a change to these notices, a new Notice to Mariners will be issued.

PRELIMINARY (P) NOTICES

- (a) When important changes affecting navigation are to take place in the near future, a Notice to Mariners describing the change will be published, so that the mariners will have advanced information on the change. Such notices will be designated (P).
- (b) When a change in conditions affecting navigation has taken place but full information is not available, a (P) notice giving available information will be published. This notice will be followed by a regular notice when complete information becomes available. The regular notice will cancel the (P) notice.
- (c) When a change has taken place which is too complex to describe in a written notice, a (P) notice giving general information will be published. This notice will explain that follow up action will be taken to update charts by publishing patch corrections, new editions or new charts.

Please note that following the expiry of the 90-day comment or objection period, Preliminary (P) Notices of proposed changes or intention to discontinue will be automatically cancelled. In the event of a change to these notices, a new Notice to Mariners will be issued.

ACTION REQUIRED ON RECEIPT OF (T) & (P) NOTICES

It is not customary to make permanent corrections to charts and publications from (T) and (P) notices. On receipt of such notices, the information they contain should be noted in pencil on the affected charts and/or the publications.

CAUTION

Mariners are reminded that charts and publications are not corrected from (T) and (P) notices when purchased from suppliers. Reference should be made to the latest list of charts affected by Temporary and Preliminary Notices published.

INDEX OF (T) & (P) NOTICES							
Notice #	Page	Notice #	Page	Notice #	Page	Notice #	Page
616(T)/07	1	1218(T)/16	7	417(T)/19	11	612(P)/19	17
909(T)/14	2	1219(T)/16	7	512(P)/19	11	613(P)/19	18
1005(T)/15	3	108(T)/17	8	513(P)/19	12	614(P)/19	18
1105(T)/15	3	113(T)/17	8	514(P)/19	12, 13	615(P)/19	19
515(T)/16	4	309(T)/17	8	607(P)/19	14	713(P)/19	19
814(T)/16	4	1205(T)/17	9	608(P)/19	15	714(P)/19	20
818(T)/16	4	1206(T)/17	9	609(P)/19	16	715(P)/19	20
819(T)/16	5, 6	709(T)/18	10	610(P)/19	16	716(T)/19	20
1011(T)/16	7	809(T)/18	10	611(P)/19	17		

	INDEX OF CHARTS AFFECTED BY (T) & (P) NOTICES						
Chart	Page	Chart	Page	Chart	Page	Chart	Page
2017	2, 10	2123	8	4277	11	4839	17
2044	3	2181	8	4386	16	4863	18
2058	10	2235	4	4405	12	4885	18
2060	4	2315	4	4426	12, 13, 20	6022	9
2067	7	3540	19	4455	16	6287	8
2077	7	4235	14	4615	20		
2085	9, 11	4236	15	4622	17		
2086	7	4241	19	4832	20		

*616(T) DEMARCATION BAY TO/À PHILIPS BAY - MOBILE OFFSHORE DRILLING UNIT TEMPORARILY ESTABLISHED

The unmanned mobile offshore drilling unit "SDC" has been temporarily established at 69° 24.71'N 138° 53.76'W. The unit is marked with a light FI R, the structure is 202.4 metres long and 53 metres wide.

For information, contact Captain Connelly at 1-250-598-4513 or 1-250-744-9818 or e-mail doncon@islandnet.com

(NOTSHIP H0212/06, Sarnia, June 2007)

*909(T) KINGSTON HARBOUR AND APPROACHES/ET LES APPROCHES – DOCK UNSERVICEABLE

Reference Chart: 2017

The Kingston psychiatric hospital dock is unserviceable and out of bounds for use as dockage until further notice.

(NOTSHIP C2409/10)

*1005(T) PORT DALHOUSIE - EAST AND WEST PIERS – ACCESS FORBIDDEN

Reference Chart: 2044

A recent engineering investigation identified structural issues and safety concerns with both the East and West piers at Port Dalhousie. In light of the inspection findings, the Department of Fisheries and Oceans is taking action to protect the safety of the public by prohibiting vessel, vehicular, and pedestrian access to the piers.

Vessels can still safely navigate the waters surrounding the piers, but will be unable to moor at the piers. The City of St. Catharines will accommodate boaters as possible at other local wharves.

Mark Sandeman Area Manager, Client Services Small Craft Harbours Central & Arctic Region Fisheries and Oceans Canada

3027 Harvester Road, Unit 310 Burlington, ON L7N 3G7 Telephone: (905) 639-2050 Facsimile: (905) 639-5975

Email: mark.sandeman@dfo-mpo.gc.ca

(NOTSHIP C567/15)

*1105(T) CANADA – SAFETY OF OFFSHORE EXPLORATION AND EXPLOITATION VESSELS

Reference: Notice 410(T)/2007 is cancelled.

2015 Annual Edition of Notices to Mariners, Notice No. 20, pages A20-1 to A20-4.

Mariners are advised that offshore exploration and exploitation vessels may be conducting drilling operations in the following areas:

Gulf of St. Lawrence

NIL

Mainland NWT

NII

Mackenzie Delta NWT/Beaufort Sea

NII

Arctic Islands of the NWT/Arctic Islands of Nunavut

NII

Eastern Arctic Offshore

NIL

Davis Strait

NIL

NOTE: Mariners are advised to obtain up-to-date position reports on drilling vessels and production installations before entering an area of exploration and exploitation. This information is available by contacting, as appropriate, ECAREG CANADA, NORDREG CANADA or CVTS OFFSHORE via any Marine Communications and Traffic Services Centre (MCTS).

(NOTSHIP M2215/15) (NEB)

*515(T) HARBOURS ON THE EAST SHORE OF LAKE SUPERIOR/PORTS SUR LA RIVE EST DU LAC SUPÉRIEUR – BUOYS TEMPORARILY DISCONTINUED

Reference Chart: 2315

The Canadian Coast Guard has temporarily discontinued the following aids to navigation: XT1, XT2, XT3, XT4, XT5, XT6, XT7, XT8, XT9, XT10, XT11, XT12.

(NOTSHIP C1045)

*814(T) MAIN DUCK ISLAND TO/À SCOTCH BONNET ISLAND – PARTIALLY SUBMERGED FIXED STEEL BARGES

Reference Chart: 2060

There are 3 partially submerged fixed steel barges in North end of West Lake (43° 57' 02.3"N 077° 20' 12.8"W), which have been reported just below the water line.

Barges are marked with cautionary buoys.

(NOTSHIP C1641/14)

*818(T) CAPE HURD TO/À LONELY ISLAND – LIGHT CHARACTERISTICS TEMPORARILY CHANGED

Reference Chart: 2235

The light characteristics of Cove Island (LL 805) (U.S. LL 12675) have temporarily changed to flash 1 second, eclipse 9 seconds and night-time operation only.

(NOTSHIP C2522/11)

*819(T) AUTOMATIC IDENTIFICATION SYSTEM (AIS)

AIS Application-Specific Messages (ASM) and AIS AtoN

Mariners are advised that the Canadian Coast Guard will perform a test of AIS Application-Specific Messages (AIS-ASM) on the Pacific Coast from the Sand Heads meteorological/hydrological station: 49°06'21"N 123°18'12"W, and may extend this testing to other stations in the coming months. The test will start at the end of August and consist of broadcasting meteorological/hydrological (MET/HYDRO) data through AIS binary "Message 8".

Although AIS was originally developed as a means for positive identification and tracking of ships, it includes functionalities to transmit binary messages such as MET/HYDRO information and other types of data. These additional functionalities of AIS may be useful to mariners to assist in onboard voyage planning.

Ships need to be equipped with a proper Class "A" AIS device for the accurate onboard display of AIS message. The IMO mandatory carriage requirement for the Class "A" AIS display¹ is the Minimum Keyboard Display (MKD) which displays the binary data in an alphanumeric form. However, as there is no current requirement for the MKD to be capable of decoding all AIS binary messages, the display and use of the ASM information may require additional hardware and/or software².

AIS Aids to Navigation (AtoN)

The International Association of Marine Aids to Navigation and Lighthouse Authorities (IALA) defines an AtoN as:

'a device or system external to vessels that is designed and operated to enhance the safe and efficient navigation of vessels and/or vessel traffic'.3

The primary purpose of an AIS AtoN Station is to promote and enhance safety and efficiency of navigation by one or more of the following:

- Providing a positive and all-weather means of identification;
- Complementing existing services (e.g. RACONS) from AtoN;
- Transmitting accurate positions of floating AtoN;
- Indicating if a floating AtoN is off position (monitoring the status of an AtoN);
- Marking or delineating tracks, routes, areas, and limits;
- Marking offshore structures:
- Enable timely marking of new hazards (fixed or dynamic) using Virtual AIS AtoN.

The use of AIS within the marine aids to navigation service is accomplished by the broadcasting of the aids to navigation report message "Message 21".

An AIS AtoN can be implemented in three ways, Real, Synthetic, and Virtual.

- 1) Physical/real AIS AtoN: An AIS device which is physically located on the AtoN and transmits "Message 21".
- 2) Synthetic AIS AtoN: There are 2 types of Synthetic AIS AtoN Monitored and Predicted.
 - a. Monitored: A "Message 21" is transmitted from a nearby AIS base station. The AtoN physically exists but there is no AIS device on it. A communication link is installed on the AtoN to allow the monitoring of its status
 - b. <u>Predicted</u>: A "Message 21" is transmitted from a nearby AIS base station. The AtoN physically exists but there is neither an AIS device on it nor a communication link. Status and position of the AtoN cannot be monitored.
- Virtual AIS AtoN: A "Message 21" is transmitted from a nearby AIS base station for an AtoN that does not physically exist. The "Message 21" will clearly identify this as a virtual AIS AtoN.

¹ Class A AIS units are those meeting the mandatory SOLAS carriage requirements (SOLAS Chapter V, Rule 19) for vessels over 300GRT. Class B AIS units are for use on craft that are not covered by the mandatory carriage requirements.

² IALA Guideline No. 1095 On Harmonised implementation of Application-Specific Messages (ASMs) Edition 1 May 2013.

³ IALA Recommendation A-126 On The Use of the Automatic Identification System (AIS) in Marine Aids to Navigation Services Edition 1.5 June 2011 Edition 1; June 2004.

Displays and Symbology

As the AIS information available to mariners will be dependent on their display system, **not all transmitted information may be displayed**. Mariners are encouraged to install systems that provide AIS overlay on either ECDIS or Radar, or both.

Of those vessels that are AIS equipped the various displays available can range from no display on some Class B units, through to the mandatory Class A MKD, and to a full ECDIS or Radar overlay. In the absence of an ECDIS or Radar overlay, mariners will not be able to fully utilize the AIS AtoN functionality. Also note that there is a variance in the information that can be displayed on ECDIS or Radar equipment by the different AIS manufacturers.

The symbology that may be displayed on nautical charts, display systems and the MKD is summarised below.

Nautical Charts

On nautical charts AIS AtoN are indicated by a magenta circle surrounding the existing AtoN symbol and an adjacent legend stating AIS. The font will be straight for fixed AtoN and italic for floating AtoN.



A physical AIS AtoN provided as an overlay on ECDIS, Radar or other display systems are indicated by a diamond shape with crossed lines at the reported position of the AtoN. A physical AIS AtoN that is off position will use the same symbol but in red. A virtual AIS AtoN is indicated by a dotted line diamond shape with the crossed lines at the reported position.

Physical AIS Aton



Physical AIS AtoN off position



Virtual AIS AtoN



Minimum Keyboard Display

The mandatory MKD is only required to display data in alphanumeric form. Some MKD are units supplemented by a small graphical display. Exact presentation will vary but this layout below would be typical of MKD displays.

Range	Bearing	Name
XX.XX	XXX.X	XXXXXXXX
XX.XX	XXX.X	XXXXXXXX
XX.XX	XXX.X	XXXXXXXX
Latitude	e XX	x xx.xxx
Longitu	de XX	X XX.XXX

Feedback on AIS-ASM

Mariners are requested to provide feedback on the AIS-ASM test bed to their applicable Regional MCTS Office.

Contact information can be found in the publication Radio Aids to Marine Navigation, Part 1.

*1011(T) LAKE ONTARIO/LAC ONTARIO (WESTERN PORTION/PARTIE OUEST) – SILTING REPORTED

Reference Chart: 2077

Silting reported in main entrance channel to Fifty Point Marina. Centre of channel depth reported to be 1.9 metres with shallower depths on the sides.

Mariners are requested to use caution in the area.

(NOTSHIP C2266/16)

*1218(T) HAMILTON HARBOUR - SILTING REPORTED

Reference Chart: 2067

Silting reported along the North faces of Pier 11 and Pier 12:

Pier 11 North Face between positions 43° 16' 31"N 079° 50' 56"W and 43° 16' 29"N 079° 50' 49"W, and at position 43° 16' 28"N 079° 50' 42"W.

Pier 12 North Face between positions 43° 16' 27"N 079° 50' 39"W and 43° 16' 26"N 079° 50' 33"W.

Mariners are requested to use caution and reduce speed upon arrival and departure. Seaway draft will be affected when water level is less than 0.70 metres above chart datum in these areas.

(NOTSHIP C1831/13)

*1219(T) TORONTO TO/À HAMILTON - CONSTRUCTION OPERATIONS

Reference Chart: 2086

Construction operations taking place from November 14, 2016 until approximately 2026 at Lakeview Water Treatment Plant between Marie Curtis Park and Serson Creek. A variety of equipment will be used to expand the land mass along the shoreline. Landfill and 3 islands will be lit and marked.

(NOTSHIP C2533/16)

*108(T) HARBOURS IN LAKE ERIE/HAVRES DANS LE LAC ÉRIÉ – UNLIT BUOYS TEMPORARILY REPOSITIONED

Reference Chart: 2181

The following unlit spar buoys have been temporarily repositioned due to silting:

ES2 (LL 7169) to position 42° 39' 10.0"N 081° 12' 32.0"W ES3 (LL 7170) to position 42° 39' 15.4"N 081° 12' 40.7"W ES4 (LL 7171) to position 42° 39' 16.8"N 081° 12' 37.7"W

The shallowest depth to 3.5M occurs between ES3 and ES4 with the deepest water off the red side of the channel. Mariners are requested to use caution in the area.

(B2017-003)

*113(T) MINAKI TO/À KENORA – DAYBEACON REPORTED LEANING

Reference Chart: 6287

The daybeacon DB - Q64 (LL 5635) (49° 51' 06.0"N 094° 34' 44.0"W) has been reported leaning.

(D2016-016)

*309(T) PELEE PASSAGE TO/À LA DETROIT RIVER – LOW WATER LEVELS REPORTED

Reference Chart: 2123

Low water levels have been reported from the south end of the entrance to Sturgeon Creek Harbour northward.

Annette Winter Project and Divestiture Officer Small Craft Harbours Fisheries and Oceans Canada

Canada Centre for Inland Waters (CCIW) 867 Lakeshore Road Burlington, ON L7S 1A1 Telephone: (905) 315-5286

Email: annette.winter@dfo-mpo.gc.ca

(NOTSHIP C58/13)

*1205(T) TORONTO HARBOUR -BREAKWATER ENTRANCE TO MARINA CLOSED DUE TO THE COLLAPSE OF THE BREAKWATER

Reference Chart: 2085

The breakwater entrance to the west of Ontario Place Marina has been closed due to the collapse of the breakwater.

Sub-surface hazards exist in the breakwater gap and on the inner and outer edge of the breakwater wall.

Green spar buoy BW1 has been removed, and 3 white and orange keep out markers have been placed in the breakwater entrance.

The outer edge of the breakwater wall is marked with 2 white and orange keep out markers.

The inner edge of the breakwater wall is marked with 3 white and orange keep out markers.

(NOTSHIP C79/13)

*1206(T) LAKE ROSSEAU AND/ET LAKE JOSEPH - UNLIT BUOY TEMPORARY ESTABLISHED

Reference Chart: 6022

The following unlit buoy has been temporary established:

P3/1 (LL 9089.1) (45° 08' 09.0"N 079° 40' 36.0"W)

(D2017-006)

*709(T) KINGSTON HARBOUR AND APPROACHES/ET LES APPROCHES – INFORMATION REGARDING MOORING AND ANCHORING

Reference: Notice 309(T)/14 is cancelled.

Reference Chart: 2017

All mooring or anchoring within the public port of Kingston is prohibited outside of designated marina areas until further notice without authorization from the port official.

Inquiries are to be directed to Transport Canada at (416) 952-0475.

*809(T) COBOURG TO/À OSHAWA - DREDGING OPERATIONS

Reference Chart: 2058

Dredging operations in Port Hope Harbour from August 3, 2018 until December 30, 2022. A wave attenuator will block the entrance to the western basin.

Mariners are requested to stay clear of the area.

(NOTSHIP C1951/18)

*417(T) TORONTO HARBOUR – CONSTRUCTION OPERATIONS

Reference Chart: 2085

Construction operations in position 43° 36' 46.84"N 079° 23' 27.99"W and marked by a line of yellow cautionary buoys from September 2018 to December 2020. Tug and barge operation will be placing stone in the water to 0.3 m above chart datum.

Vessels in the area are advised to keep clear of the operation and to contact David G on VHF channel 16 or at 416-938-9607.

*512(P) GREAT BRAS D'OR, ST. ANDREWS CHANNEL AND/ET ST. ANNS BAY – FOG SIGNAL TO BE PERMANENTLY DISCONTINUED

Reference Chart: 4277

The Canadian Coast Guard proposes to permanently discontinue the fog signal on the following aid to navigation:

Black Rock Point (LL 799) (46° 18' 18.8"N 060° 23' 29.8"W): The light and structure to remain.

Comments on this action are solicited from mariners and other interested parties by August 31, 2019, three months following the initial publication date of May 31, 2019. Following this date, this notice will be cancelled. Comments should be directed to the following:

Superintendent, Renee Pope Aids to Navigation and Waterways Canadian Coast Guard P.O. Box 5667 St. John's, NL A1C 5X1 Telephone: (709) 772-2800

Email: renee.pope@dfo-mpo.gc.ca

Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(G2019-038)

*513(P) PICTOU ISLAND TO / AUX TRYON SHOALS - NOTICE OF PROPOSED CHANGES

Reference Chart: 4405

The Canadian Coast Guard proposes to permanently change the following aids to navigation:

LL#	Aid Name	Position	Proposed Changes
1008.	Victoria Harbour	46° 12' 50.8"N 063° 29' 19.7"W	Discontinue aid.
1008.	Victoria Harbour Wharf Light	N/A	Establish new light in position 46° 12.746'N 063° 29.339'W. The light will be green (flash 1 s; eclipse 3 s) and be equipped with a port daybeacon.

Comments on this action are solicited from mariners and other interested parties by August 31, 2019, three months following the initial publication date of May 31, 2019. Following this date, this notice will be cancelled. Comments should be directed to the following:

Superintendent, Renee Pope Aids to Navigation and Waterways Canadian Coast Guard P.O. Box 5667 St. John's, NL A1C 5X1

Telephone: (709) 772-2800 Email: renee.pope@dfo-mpo.gc.ca

Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(G2019-040)

*514(P) RIVIÈRE RISTIGOUCHE / RESTIGOUCHE RIVER - NOTICE OF PROPOSED CHANGES

Reference Chart: 4426

The Canadian Coast Guard proposes to permanently change the following aids to navigation:

Fixed Aids					
LL#	Aid Name	Position	Proposed Changes		
1343	Inch Arran Point range front	48° 03' 39.4"N 066° 21' 03.4"W	Increase intensity of lantern.		
1343.1	Inch Arran Point range rear	286°45' 364.5 m from front.	Increase intensity of lantern. Change flash characteristics to Iso 6s operating 24 h.		
1343.6	Dalhousie Wharf	48° 04' 17.8"N 066° 21' 37.0"W	Decrease intensity of lantern.		
1343.7	Dalhousie Harbour East range front	48° 04' 15.2"N 066° 21' 57.3"W	Change flash characteristics to fixed. Decrease intensity of lantern.		
1343.8	Dalhousie Harbour East range rear	268°10' 49.4 m from front.	Change flash characteristics to fixed. Decrease intensity of lantern.		
1345.4	Dalhousie Harbour range front	48° 04' 20.6"N 066° 22' 10.4"W	Discontinue range light. Establish port hand light (flash 1 s; eclipse 3 s) in current position and add 2 port hand daybeacons.		
1345.5	Dalhousie Harbour range rear	264°24' 614.4 m from front.	Discontinue range light and daymark.		

	Floating Aids						
LL#	Aid Name	Position	Proposed Changes				
1343.2	Dalhousie Harbour light buoy EX2	48° 04' 25.3"N 066° 21' 25.8"W	Renumber buoy EX2 to EX4. Relocate to position 48° 04' 25.6"N 066° 21' 25.9"W. Increase light intensity.				
1343.3	Dalhousie Harbour light buoy EX4	48° 04' 25.4"N 066° 21' 44.9"W	Renumber buoy EX4 to EX6. Relocate to position 48° 04' 25.9"N 066° 21' 44.7"W. Increase light intensity.				
1343.4	Dalhousie Harbour light buoy EX6	48° 04' 25.5"N 066° 21' 55.9"W	Renumber buoy from EX6 to EX8. Relocate to position 48° 04' 25.7"N 066° 21' 55.7"W. Increase light intensity.				
1345.6	Dalhousie Harbour light buoy EX7	48° 04' 16.2"N 066° 23' 14.9"W	Renumber buoy from EX7 to EX9. Relocate to approximate position 48° 04' 15.9"N 066° 23' 08.2"W. Remove lantern and renumber LL 6345.6.				
1362	Banc Miguasha light buoy EV2	48° 03' 24.2"N 066° 18' 57.9"W	Renumber buoy from EV2 to EX2. Increase light intensity.				
1362.1	Rivière Restigouche light buoy EY1	48° 04' 12.2"N 066° 21' 21.9"W	Renumber buoy from EY1 to EX3. Relocate to position 48° 04' 13.2"N 066° 21' 19.4"W. Increase intensity and rename buoy "East Bay Light Buoy EX3."				
6347	Middle Ground buoy EV3	48° 05' 02.2"N 066° 21' 35.9"W	Change from porthand buoy to north cardinal buoy. Rename "Middle Ground North Cardinal buoy EV." Change from SB98 to SB60 or GDI 500/800 type of buoy.				
6353.1	Restigouche River EW2	48° 04' 51.2"N 066° 22' 01.9"W	Discontinue buoy.				

Comments on this action are solicited from mariners and other interested parties by August 31, 2019, three months following the initial publication date of May 31, 2019. Following this date, this notice will be cancelled. Comments should be directed to the following:

Superintendent, Renee Pope Aids to Navigation and Waterways Canadian Coast Guard P.O. Box 5667 St. John's, NL A1C 5X1 Telephone: (709) 772-2800

Email: renee.pope@dfo-mpo.gc.ca

Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(G2019-035, 036)

*607(P) BARREN ISLAND TO / À TAYLORS HEAD - FOG SIGNAL TO BE DISCONTINUED

Reference Chart: 4235

The Canadian Coast Guard proposes to permanently discontinue the fog signal on the following aid to navigation:

Beaver Island (LL 602) (44° 49' 29.2"N 062° 20' 16.0"W): The light and structure to remain.

Comments on this action are solicited from mariners and other interested parties by September 27, 2019, three months following the initial publication date of June 28, 2019. Following this date, this notice will be cancelled. Comments should be directed to the following:

Superintendent, Renee Pope Aids to Navigation and Waterways Canadian Coast Guard P.O. Box 5667 St. John's, NL A1C 5X1 Telephone: (709) 772-2800

Email: renee.pope@dfo-mpo.gc.ca

Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(F2019-012)

*608(P) TAYLORS HEAD TO / À SHUT-IN ISLAND - NOTICE OF PROPOSED CHANGES

Reference Chart: 4236

The Canadian Coast Guard proposes to permanently change the following aids to navigation:

LL#	Aid Name	Position	Proposed Changes
5586.01	Ship Harbour buoy YM8	44° 46' 18.5"N 062° 47' 55.0"W	Establish red lantern with flash characteristics: Flash 0.5 s; eclipse 3.5 s. Suggested Aid Name: Black Rock light buoy YM8. Suggested LL Number: 586.01
5586.03	Ship Harbour buoy YM12	44° 46′ 57.0″N 062° 49′ 09.3″W	Establish red lantern with flash characteristics: Flash 0.5 s; eclipse 3.5 s. Suggested Aid Name: Ship Harbour light buoy YM12. Suggested LL Number: 586.03
5586.04	Ship Harbour buoy YM14	44° 47' 57.2"N 062° 50' 10.0"W	Establish red lantern with flash characteristics: Flash 0.5 s; eclipse 3.5 s. Suggested Aid Name: Ship Harbour light buoy YM14. Suggested LL Number: 586.04
5586.07	Ship Harbour buoy YM17	44° 48' 08.0"N 062° 50' 30.1"W	Establish green lantern with flash characteristics: Flash 0.3 s; eclipse 0.7 s. Suggested Aid Name: Ship Harbour light buoy YM17. Suggested LL Number: 586.07
5586.09	Ship Harbour buoy YM23	44° 48' 23.5"N 062° 51' 31.8"W	Reposition to 44° 48' 24.1"N 062° 51' 36.0"W.

Comments on this action are solicited from mariners and other interested parties by September 27, 2019, three months following the initial publication date of June 28, 2019. Following this date, this notice will be cancelled. Comments should be directed to the following:

Superintendent, Renee Pope Aids to Navigation and Waterways Canadian Coast Guard P.O. Box 5667 St. John's, NL A1C 5X1

Telephone: (709) 772-2800

Email: renee.pope@dfo-mpo.gc.ca

Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(F2019-013)

*609(P) ST. MARGARET'S BAY - NOTICE OF PROPOSED CHANGES

Reference Chart: 4386

The Canadian Coast Guard proposes to permanently change the following aid to navigation:

LL#	Aid Name	Position	Proposed Changes
488	Dover	44° 29' 24.3"N 063° 51' 40.7"W	Change the function of the aid to Port Bifurcation and the flash characteristics to FI(2+1) 6s. The aid will maintain a port bifurcation daymark.

Comments on this action are solicited from mariners and other interested parties by September 27, 2019, three months following the initial publication date of June 28, 2019. Following this date, this notice will be cancelled. Comments should be directed to the following:

Superintendent, Renee Pope Aids to Navigation and Waterways Canadian Coast Guard P.O. Box 5667 St. John's, NL A1C 5X1 Telephone: (709) 772-2800

Email: renee.pope@dfo-mpo.gc.ca

Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(F2019-011)

*610(P) BAIE WASHTAWOUKA À/TO BAIE PIASHTI – RANGE LIGHTS TO BE DISCONTINUED

Reference Chart: 4455

The Canadian Coast Guard proposes to permanently discontinue the following aids to navigation:

Aguanish range front (LL 1580) (50° 13' 05.8"N 062° 05' 00.4"W) Aguanish range rear (LL 1581) (330°29' 478.7 m from front)

Comments on this action are solicited from mariners and other interested parties by September 27, 2019, three months following the initial publication date of June 28, 2019. Following this date, this notice will be cancelled. Comments should be directed to the following:

Superintendent, Lise Richard Aids to Navigation & Waterways, Central & Arctic Region Canadian Coast Guard 101 boulevard Champlain Québec, QC G1K 7Y7

Telephone: (418) 648-7450 Email: <u>lise.richard@dfo-mpo.gc.ca</u>

Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(Q2019-086)

*611(P) CAPE ST MARY'S TO / À ARGENTIA HARBOUR AND / ET JUDE ISLAND - FOG SIGNAL TO BE DISCONTINUED

Reference Chart: 4622

The Canadian Coast Guard proposes to permanently discontinue the fog signal on the following aid to navigation:

Marticot Island (LL 50) (47° 19' 36.8"N 054° 34' 52.8"W): The light and structure to remain.

Comments on this action are solicited from mariners and other interested parties by September 27, 2019, three months following the initial publication date of June 28, 2019. Following this date, this notice will be cancelled. Comments should be directed to the following:

Superintendent, Renee Pope Aids to Navigation and Waterways Canadian Coast Guard P.O. Box 5667 St. John's, NL A1C 5X1 Telephone: (709) 772-2800

Email: renee.pope@dfo-mpo.gc.ca

Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(N2019-039)

*612(P) HEAD OF / FOND DE PLACENTIA BAY – LIGHT TO BE DISCONTINUED

Reference Chart: 4839

The Canadian Coast Guard proposes to permanently discontinue the following aid to navigation:

Swift Current Wharf (LL 41) (47° 52' 42.8"N 054° 12' 03.0"W)

Comments on this action are solicited from mariners and other interested parties by September 27, 2019, three months following the initial publication date of June 28, 2019. Following this date, this notice will be cancelled. Comments should be directed to the following:

Superintendent, Renee Pope Aids to Navigation and Waterways Canadian Coast Guard P.O. Box 5667 St. John's, NL A1C 5X1 Telephone: (709) 772-2800

Email: renee.pope@dfo-mpo.gc.ca

Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(N2019-033)

*613(P) BACALHAO ISLAND TO / À BLACK ISLAND - LIGHT TO BE DISCONTINUED

Reference Chart: 4863

The Canadian Coast Guard proposes to permanently discontinue the following aid to navigation:

Comfort Cove Wharf (LL 353.9) (49° 24' 19.7"N 054° 51' 17.2"W)

Comments on this action are solicited from mariners and other interested parties by September 27, 2019, three months following the initial publication date of June 28, 2019. Following this date, this notice will be cancelled. Comments should be directed to the following:

Superintendent, Renee Pope Aids to Navigation and Waterways Canadian Coast Guard P.O. Box 5667 St. John's, NL A1C 5X1 Telephone: (709) 772-2800

Email: renee.pope@dfo-mpo.gc.ca

Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(N2019-035)

*614(P) PORT HARMON AND APPROACHES / ET LES APPROCHES – LIGHTS TO BE DISCONTINUED

Reference Chart: 4885

The Canadian Coast Guard proposes to permanently discontinue the following aids to navigation:

Port Harmon Southwest Breakwater (LL 180.12) (48° 30' 29.3"N 058° 32' 17.0"W) Port Harmon Channel (LL 180.3) (48° 30' 38.5"N 058° 32' 21.9"W)

Comments on this action are solicited from mariners and other interested parties by September 27, 2019, three months following the initial publication date of June 28, 2019. Following this date, this notice will be cancelled. Comments should be directed to the following:

Superintendent, Renee Pope Aids to Navigation and Waterways Canadian Coast Guard P.O. Box 5667 St. John's, NL A1C 5X1 Telephone: (709) 772-2800

Email: renee.pope@dfo-mpo.gc.ca

Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(N2019-032)

*615(P) APPROACHES TO/APPROCHES À CAMPBELL RIVER - RANGE LIGHTS TO BE DISCONTINUED

Reference Chart: 3540

The Canadian Coast Guard proposes to permanently discontinue the following aids to navigation:

Tyee Spit range front (LL 512.6) (50° 02' 53.1"N 125° 15' 34.2"W) Tyee Spit range rear (LL 512.7) (205°42' 50.9 m from front)

Comments on this action are solicited from mariners and other interested parties by September 27, 2019, three months following the initial publication date of June 28, 2019. Following this date, this notice will be cancelled. Comments should be directed to the following:

A/Superintendent, Glenna Evans
Aids to Navigation & Waterways, Western Region
Canadian Coast Guard
25 Huron Street
Victoria, BC V8V 4V9
Telephone: (250) 480-2602
Fax: (250) 480-2702

Email: glenna.evans@dfo-mpo.gc.ca

Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(P2019-073)

*713(P) LOCKEPORT TO / À CAPE SABLE - SOUND SIGNALS TO BE DISCONTINUED

Reference Chart: 4241

The Canadian Coast Guard proposes to permanently discontinue the bell and whistle, respectively, from the following aids to navigation:

Budget Rock light and bell buoy SN51 (LL 350) (43° 31' 35.0"N 065° 20' 41.5"W) Negro Harbour light and whistle buoy SN (LL 353) (43° 31' 01.5"N 065° 18' 50.0"W)

The buoys and their lights will remain.

Comments on this action are solicited from mariners and other interested parties by October 25, 2019, three months following the initial publication date of July 26, 2019. Following this date, this notice will be cancelled. Comments should be directed to the following:

Superintendent, Renee Pope Aids to Navigation and Waterways Canadian Coast Guard P.O. Box 5667 St. John's, NL A1C 5X1 Telephone: (709) 772-2800

Email: renee.pope@dfo-mpo.gc.ca

Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(F2019-024)

*714(P) HARBOURS IN PLACENTIA BAY / HAVRES DANS PLACENTIA BAY: PETIT FORTE TO / À BROAD COVE HEAD – LIGHT TO BE DISCONTINUED

Reference Chart: 4615

The Canadian Coast Guard proposes to permanently discontinue the following aid to navigation:

Baine Harbour Floating Dock (LL 55.42) (47° 21' 49.3"N 054° 53' 53.5"W)

Comments on this action are solicited from mariners and other interested parties by October 25, 2019, three months following the initial publication date of July 26, 2019. Following this date, this notice will be cancelled. Comments should be directed to the following:

Superintendent, Renee Pope Aids to Navigation and Waterways Canadian Coast Guard P.O. Box 5667 St. John's, NL A1C 5X1 Telephone: (709) 772-2800

Email: renee.pope@dfo-mpo.gc.ca

Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(N2019-041)

*715(P) FORTUNE BAY: SOUTHERN PORTION / PARTIE SUD - LIGHT TO BE DISCONTINUED

Reference Chart: 4832

The Canadian Coast Guard proposes to permanently discontinue the following aid to navigation:

Grand Bank Floating Dock (LL 106.51) (47° 05' 57.4"N 055° 45' 02.9"W)

Comments on this action are solicited from mariners and other interested parties by October 25, 2019, three months following the initial publication date of July 26, 2019. Following this date, this notice will be cancelled. Comments should be directed to the following:

Superintendent, Renee Pope Aids to Navigation and Waterways Canadian Coast Guard P.O. Box 5667 St. John's, NL A1C 5X1 Telephone: (709) 772-2800

Email: renee.pope@dfo-mpo.gc.ca

Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(N2019-040)

*716(T) RIVIÈRE RISTIGOUCHE / RESTIGOUCHE RIVER - FEDERAL WHARF CLOSED TO NAVIGATION

Reference Chart: 4426

The federal wharf at Miguasha is closed to navigation. For reasons of safety and because of the collapsing risk, it is not permitted to berth at the wharf or to come closer than 20 meters from these structures.

For more information, please contact the regional representative of port operations at Transport Canada, Quebec region, Mme Myriam Rouleau at 418-446-8402.

(NAVWARN NW-Q-0318-16)